

Operator destacking/emptying pallets from the racks inadvertently caught and dragged back a full pallet from the level above which landed on the roof of the FLT damaging and shattering the roof windscreen. The metal pallet then slid down the chassis of the FLT landing on the floor.

! " # ! \$

% # # &# ! ! &! % ' !& # ()% ! # \$! # \$!!& % *+,-",./ *+%/& !&0 # ()% !&0 # () (0 # % ,/1,-