

RIDDOR - Misfire - nothing unusual noted at time of blast.

WHAT HAPPENED

2 days later an unfired detonator and primer were found in shotpile. Subsequent clearance operations revealed a failure of connection between holes which meant 5 holes had misfired.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	18/09/2024 12:46:30
SUB ACTIVITY:	FACE ACTIVITY	INCIDENT No:	04821