

TRANSPORT - Runaway - Rear trailer became detached at concrete products plant and careered through fencing

WHAT HAPPENED

A drawbar vehicle was loaded with concrete blocks. On leaving site onto the main haul road, the rear trailer became detached/uncoupled and careered through fencing onto a neighbouring building site. Site operative jumped out of the way but was caught on his arm/hand by the fencing, causing minor abrasions.

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: TRANSPORT & LOGISTICS / DELIVERY
SUB ACTIVITY: BRAKES AND RUNAWAYS

ALERT STATUS: Normal
DATE ISSUED: 06/06/2025 12:24:44
INCIDENT No: 04898