

## INCIDENT ALERT

**LOCATION:** Mobile Plant

**ALERT STATUS:** Normal

**ACTIVITY:** Manual handling and storage

**DATE ISSUED:** 14/05/08

**SUB ACTIVITY:** N/A

**INCIDENT No:** 00162

### TITLE

Mobile Fuel Bowser

### ACCIDENT / INCIDENT DETAILS

Modifications have been made to a diesel bowser battery position.

The battery was originally fitted inside the housing of the diesel bowser. This meant that it was extremely difficult to lift the battery out of the housing when it had to be charged.

### ACCIDENT / INCIDENT IMAGES



Original battery position with restricted access

### LEARNING POINTS / ACTIONS TAKEN

To prevent lifting injuries the Penderyn fitters have placed a box on the outside. It is away from any diesel spillage run off which could have been a fire risk during the re-charging process.

If you have bowzers on your sites please inform your fitter of this modification.

### LEARNING POINTS / ACTIONS IMAGES



New external battery location