

Delivery vehicle reversing towards spreader with body raised and twist locks / pins were removed. The rear tipper body door burst open, due to the weight sitting against it spilling load onto roadway

## WHAT HAPPENED

## LEARNING POINTS / ACTIONS TAKEN

---

|               |                                  |               |                     |
|---------------|----------------------------------|---------------|---------------------|
| LOCATION:     | CONSTRUCTION/DELIVERY SITE       | ALERT STATUS: | Normal              |
| ACTIVITY:     | TRANSPORT & LOGISTICS / DELIVERY | DATE ISSUED:  | 13/09/2024 12:52:13 |
| SUB ACTIVITY: | DELIVERING AGGREGATES            | INCIDENT No:  | 04802               |