

Spillage of hot material at cement plant

WHAT HAPPENED

Material backing up in pump due to oversupply - spilt out from hopper connection point onto the floor. Estimated temp of material between 168 °C and 182 °C. Occurred on maintenance day when material was diverted from the raw meal elevators to pump as per standard procedure.

LEARNING POINTS / ACTIONS TAKEN

| | | | |
|---------------|----------------------------|---------------|---------------------|
| LOCATION: | CEMENT PLANT | ALERT STATUS: | Normal |
| ACTIVITY: | MAINTENANCE & HOUSEKEEPING | DATE ISSUED: | 06/06/2025 12:18:51 |
| SUB ACTIVITY: | HOPPERS AND SILOS | INCIDENT No: | 04897 |