# Fatal 3 - Working at Height – Procedural Adherence

## WHAT HAPPENED

An operative was witnessed by client representative accessing works via the perimeter edge handrail at Level 4 as opposed to using the method set out within Project Task Plan.

Fellow operatives also working in vicinity failed to prevent unsafe actions. .

**Operative by the third column on the right**

**Operative is on 4th level**

## LEARNING POINTS / ACTIONS TAKEN

1. All operatives re-inducted by Principal Contractor

2. TBT given to all operatives relating to WAPE (Working at Perimeter Edge)

3. All operatives stood down and Safe Working Procedures re-briefed.

4. WAH checklist to be undertaken by site supervisor at location of works with sheet displayed in pouch attached to exclusion zone barrier or handrail at work face

| | | | |
|---|---|---|---|
| **LOCATION:** | **CONSTRUCTION/DELIVERY SITE** | **ALERT STATUS:** | **Normal** |
| **ACTIVITY:** | **BEHAVIOURAL SAFETY MANAGEMENT** | **DATE ISSUED:** | **13/06/2022 16:33:00** |
| **SUB ACTIVITY:** | **NO SUB ACTIVITY AVAILABLE** | **INCIDENT No:** | **03620** |