Isolation Breach - plant was re-energised prior to replacement of the head-drum guard on the batch belt.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**READYMIX OR MORTAR PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**MAINTENANCE & HOUSEKEEPING**	**DATE ISSUED:**	**03/09/2024 16:54:11**
SUB ACTIVITY:	**CONVEYORS**	**INCIDENT No:**	**03734**