Gap in ladder on stack allowed fall arrest system to come loose.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CEMENT PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**ACCESS & EGRESS & WORKING AT HEIGHT**	**DATE ISSUED:**	**11/09/2024 19:07:17**
SUB ACTIVITY:	**N/A**	**INCIDENT No:**	**03770**