Marine Sand was being loaded out to stock from underneath the radial conveyor when the stockpile failed and material slipped onto the bench and partially onto the floor.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**WHARF**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**STOCKPILING AND STACKING**	**DATE ISSUED:**	**13/09/2024 11:38:11**
SUB ACTIVITY:	**NO SUB ACTIVITY AVAILABLE**	**INCIDENT No:**	**03792**