

RIDDOR - Delivery vehicle had finished tipping off and drove off with body still lifted. The tipper body hit electric cables.

WHAT HAPPENED

Operatives on site shouted stop, but the driver didn't hear them because he had headphones on. This resulted in him driving through a main overhead electric cable and pulling it down along with the post which snapped in half.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONSTRUCTION/DELIVERY SITE	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	18/09/2024 13:08:03
SUB ACTIVITY:	DRIVER AWARENESS	INCIDENT No:	04823