Fatal 6 - Tipper loses wheel

WHAT HAPPENED

Tipper was returning empty to site after delivering a load. As the vehicle slowed to go through traffic lights the 2nd axle nearside wheel came off narrowly missing other vehicles before coming to rest on the side of the road

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**ON-HIGHWAY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**TRANSPORT & LOGISTICS / DELIVERY**	**DATE ISSUED:**	**30/05/2025 14:05:12**
SUB ACTIVITY:	**TYRES AND WHEELS**	**INCIDENT No:**	**04871**