TRANSPORT - Runaway - Rear trailer became detached at concrete products plant and careered through fencing

WHAT HAPPENED

A drawbar vehicle was loaded with concrete blocks. On leaving site onto the main haul road, the rear trailer became detached/uncoupled and careered through fencing onto a neighbouring building site. Site operative jumped out of the way but was caught on his arm/hand by the fencing, causing minor abrasions.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CONCRETE PRODUCTS PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**TRANSPORT & LOGISTICS / DELIVERY**	**DATE ISSUED:**	**06/06/2025 12:24:44**
SUB ACTIVITY:	**BRAKES AND RUNAWAYS**	**INCIDENT No:**	**04898**