Rock trap overwhelmed when approximately 20t of sand and gravel flowed on to the haul road. Unusually wet conditions - material had been deliberately dropped into the rock trap area.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**QUARRY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**PRODUCTION AND PROCESSING**	**DATE ISSUED:**	**09/06/2025 19:08:24**
SUB ACTIVITY:	**AGGREGATE PROCESSING**	**INCIDENT No:**	**04909**