Elevated Walkway Inspection

WHAT HAPPENED

During a routine site visit it was noticed that a number of the brackets securing the mesh decking to walkway and platform steelwork were loose or missing. This could have lead to a person falling through an elevated walkway or platform and being injured.



Loose Bracket

LEARNING POINTS / ACTIONS TAKEN

The company concerned advised that

- an urgent inspection of all types of elevated walkways & platforms should be undertaken

- these types of structures are included in your inspection & maintenance schemes.

LOCATION:	**COMPANY-WIDE**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**ACCESS & EGRESS & WORKING AT HEIGHT**	**DATE ISSUED:**	**17/08/2011**
SUB ACTIVITY:	**N/A**	**INCIDENT No:**	**00299**