An unattended landrover rolled approximately 10 metres away striking a conveyor steel support beam.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**QUARRY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**TRANSPORT & LOGISTICS / DELIVERY**	**DATE ISSUED:**	**11/09/2024 18:28:28**
SUB ACTIVITY:	**DRIVING**	**INCIDENT No:**	**03763**