Spillage of hot material at cement plant

WHAT HAPPENED

Material backing up in pump due to oversupply - spilt out from hopper connection point onto the floor. Estimated temp of material between 168 °C and 182 °C. Occurred on maintenance day when material was diverted from the raw meal elevators to pump as per standard procedure.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**CEMENT PLANT**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**MAINTENANCE & HOUSEKEEPING**	**DATE ISSUED:**	**06/06/2025 12:18:51**
SUB ACTIVITY:	**HOPPERS AND SILOS**	**INCIDENT No:**	**04897**