# BEST PRACTICE

| | | | |
|---|---|---|---|
| **LOCATION:** | **Quarry** | **ARTICLE YEAR** | **2006** |
| **ACTIVITY:** | **Manual handling and storage** | **COMPANY:** | **Aggregate Industries** |
| **SUB ACTIVITY:** | **N/A** | **COMPANY LOCATION:** | **Holme Park Quarry, Lancashire** |
| **BEST PRACTICE No:** | **BP317** | **COMPANY TEL:** | **01524 781441** |
| **COUNTRY OF ORIGIN:** | **United Kingdom** | | |

| **TITLE** |
|---|
| **Crusher access** |
| **ARTICLE** |
| Maintenance, repairs and inspection of the quarry's Mansfield crushers, created difficulties regarding manual handling, the lifting operations involving a crane, added to which, access for inspection, repairs and adjustments was poor.<br><br>It was decided to create a hydraulically operated door and hinged front panel to remedy these health and safety issues. This also included a mechanism for retaining the top hinged door whilst open. This system was then applied to the remaining crushers. |
| **ARTICLE IMAGES** |
| |