

Conveyor Maintenance Fatality

WHAT HAPPENED

A fatality has occurred whilst maintenance work was being undertaken on a conveyor are advised to review their risk assessments and safe systems of work.

The following information is available on [safequarry](http://safequarry.com)/[youtube](http://www.youtube.com):

Safe Guarding: This presentation is intended to raise awareness of the issues surrounding prompt review of existing guarding by management and ensure guarding standards are at level. <http://www.safequarry.com/hotTopics/Safe%20Guarding%20Jun%2010%20-%20>

Safety Alerts:

- Learning points from an incident where the light curtain failed
<http://www.safequarry.com/IncidentReports/IncidentView.aspx?kincident=1441>

- Learning points from a near miss from an improper isolation of a conveyor
<http://www.safequarry.com/IncidentReports/IncidentView.aspx?kincident=393>

Isolation Posters: Two posters designed to remind operators of the importance of following isolation procedures

<http://www.safequarry.com/resources/MPA%20Isolation%20Safety%20Poster%20Front>
<http://www.safequarry.com/resources/MPA%20Isolation%20Safety%20Poster%20Low>

Videos:

- Conveyor Demonstration Safety Unit: demonstrates hazards of conveyor nip points
<https://youtu.be/Ao6nrxcQRjY>

- Seven short videos produced by CEMEX
<http://www.safequarry.com/toolbox/CEMEXsuiteofvisualaidsonisolationproceduresLO>

- Tarmac Isolation Video
<https://www.youtube.com/watch?v=qRLvJBV1q1Y>

Toolbox Talks: on Conveyor Belt Safety
<http://www.safequarry.com/toolbox/Conveyorbeltsafety.pdf>

LEARNING POINTS / ACTIONS TAKEN

LOCATION:
ACTIVITY:
SUB ACTIVITY:

OTHER
MAINTENANCE & HOUSEKEEPING
N/A

ALERT STATUS:
DATE ISSUED:
INCIDENT No:

Normal
20/10/2016
01442