

Fatal 1 - LOTOTO – isolation standards not being followed


WHAT HAPPENED

A manager was visiting block factory and was looking for an employee to discuss an operational matter. In the area he identified an electrician operating a HMI panel. Within 30 seconds, the employee that the manager was looking for was found to emerge from behind a “mould” inside a guarded and energised area.

The manager checked both entrance gates to the area – they were shut and locked. The employee inside the guarded area emerged through the Rise and Set tunnel and climbed over the guard/fence in full view of the line manager. Investigation commenced.

Key Factors

Although there is a recognised and well-embedded LOTOTO standard – this is an example that despite frequent comprehensive briefings, people will still take short cuts and break rules.



LEARNING POINTS / ACTIONS TAKEN

- Share this incident with all sites – despite LOTOTO being embedded for many years, there are still examples of breaches of key safety behaviours that can come to light.
- Follow the fair and just culture process when investigating incidents
- Assess, support, coach and mentor site leaders in order that consistent standards are understood, achieved and managers and supervisors lead by example
- Review all guarding to ensure perimeter guarding is of correct height in order to prevent unauthorised access

LOCATION: CONCRETE PRODUCTS PLANT
ACTIVITY: GUARDING AND ISOLATION
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: Normal
DATE ISSUED: 22/06/2023 13:29:11
INCIDENT No: 03644