

FATAL 1 - LOTOTO - Failure to follow correct isolation procedures - HiPo

WHAT HAPPENED

A HiPo near miss occurred when interlocks were used as a form of isolation.

During aggregate processing, a blockage occurred within the chute under the secondary screen. To clear the blockage access to the area protected by distance guarding was required. The dedicated isolation point for the screen belt was not utilised, instead the interlock located on the access gate of the distance guard was relied on for the isolation, this was against the agreed SSW and training.



Please see downloadable pdf.

LEARNING POINTS / ACTIONS TAKEN

- Isolation procedures should always be followed and individual locks attached by anyone entering the area.
- Limit switches/interlocks must never be used as a form of isolation. These systems break the signals on a control circuit like an emergency stop button.
- Try out must always be conducted to ensure the equipment has been successfully isolated.

Further Consideration:

- Ensure anyone working on equipment are trained in LOTOTO.
- Ensure everyone knows the isolation procedures for any plant they work on and where the isolation points are.
- Check everyone/including contractors are following isolation when working on equipment.

LOCATION: QUARRY
ACTIVITY: GUARDING AND ISOLATION
SUB ACTIVITY: NO SUB ACTIVITY AVAILABLE

ALERT STATUS: High Potential
DATE ISSUED: 21/02/2024 16:59:49
INCIDENT No: 03696