

**Isolation Breach - plant was re-energised prior to replacement of the head-drum guard on the batch belt.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>READYMIX OR MORTAR PLANT</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>MAINTENANCE &amp; HOUSEKEEPING</b>	<b>DATE ISSUED:</b>	<b>03/09/2024 16:54:11</b>
<b>SUB ACTIVITY:</b>	<b>CONVEYORS</b>	<b>INCIDENT No:</b>	<b>03734</b>