

Failure to follow procedures for control of isolation keys

WHAT HAPPENED

During an examination of the vessel's isolation procedure, multiple isolation keys were found in an open container on a desk. These keys were designated for 'long-term' isolation locks due to ongoing maintenance activities; however, the keys were not controlled in accordance with company isolation procedures.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	AGGREGATE DREDGER	ALERT STATUS:	Normal
ACTIVITY:	GUARDING AND ISOLATION	DATE ISSUED:	05/06/2025 11:43:00
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04888