

Head end of conveyor left unguarded

WHAT HAPPENED

Guard had been removed from the head end of conveyor. The conveyor had to be de-isolated and started. This was discovered on the walk by inspection by a quarry operator

LEARNING POINTS / ACTIONS TAKEN

| | | | |
|---------------|---------------------------|---------------|---------------------|
| LOCATION: | CEMENT PLANT | ALERT STATUS: | Normal |
| ACTIVITY: | GUARDING AND ISOLATION | DATE ISSUED: | 06/06/2025 12:36:40 |
| SUB ACTIVITY: | NO SUB ACTIVITY AVAILABLE | INCIDENT No: | 04900 |