DISAB portable vacuum cleaner topples over

WHAT HAPPENED

DISAB Portable Vacuum toppled over at 45 degrees coming to rest against extruder guarding.

Causes

Hazard awareness - The risk of not having unit fixed was not foreseen

Systems - No procedure in place for regular inspection

Equipment - Bolt had come lose securing leg

LEARNING POINTS / ACTIONS TAKEN

LOCATION: MANUFACTURING - MINERALS ALERT STATUS: Normal

ACTIVITY: MAINTENANCE & HOUSEKEEPING DATE ISSUED: 02/12/2025 19:36:39

SUB ACTIVITY: MOBILE PLANT INCIDENT No: 04953