

BEST PRACTICE

LOCATION:
ACTIVITY:
SUB ACTIVITY:
BEST PRACTICE No:
COUNTRY OF ORIGIN:

Quarry
Production and Processing
Aggregate processing
BP2081

ARTICLE YEAR
COMPANY:
COMPANY LOCATION:
COMPANY TEL:

2021
Aggregate Industries
Westliegh Quarry
0000

TITLE		
Removal of bucket belt issues and confined space working		
ARTICLE		
Fatal 1, 4 and 5 Aggregate Industries' Westleigh Quarry had a problem with a bucket belt and straight conveyor that was lifting when empty due to a change in gradient and snagging on the tail drum. Please click on additional pdf do download entry in guide		
ARTICLE IMAGES		
Click image to enlarge  Wheels used on conveyor Click image to enlarge 		