

## BEST PRACTICE

<b>LOCATION:</b>	Quarry	<b>ARTICLE YEAR:</b>	2005
<b>ACTIVITY:</b>	Maintenance & Housekeeping	<b>COMPANY:</b>	Tarmac Southern
<b>SUB ACTIVITY:</b>	N/A	<b>COMPANY LOCATION:</b>	Park Farm Quarry, Bury St. Edmunds
<b>BEST PRACTICE No:</b>	BP107	<b>COMPANY TEL:</b>	01284 728931

### TITLE

Changing bucket toe-plate

### ARTICLE

At Park Farm Quarry (Tarmac Southern, Bury St. Edmunds), the manual handling risks involved in changing a toe-plate have been substantially reduced, principally by the purchase of a torque multiplier (10:1 gearing) and the fabrication of a stand to support the toe-plate at waist height.

### ARTICLE IMAGES