

BEST PRACTICE

LOCATION: Quarry
ACTIVITY: Public Perception
SUB ACTIVITY: N/A
BEST PRACTICE No: BP196

ARTICLE YEAR: 2003
COMPANY: Aggregate Industries
COMPANY LOCATION: Marybank Quarry, Isle of Lewis
COMPANY TEL: 01851 703227

TITLE

Entrance improvements

ARTICLE

When the local community began making environmental improvements to the village, Marybank Quarry decided to make its own entrance more attractive and safer.

The original entrance was narrow and at a slight angle to the adjoining road, making visibility a problem. The situation has been remedied by removing several metres of stone walling and re-aligning the road. Other improvements include new kerbs to ensure that surface water drains away, stone walling, a resurfaced road entrance, and new timber gates.

ARTICLE IMAGES



Entrance improvements