

# BEST PRACTICE

**LOCATION:**  
**ACTIVITY:** Production and Processing  
**SUB ACTIVITY:** Asphalt & coated stone  
**BEST PRACTICE No:** BP529

**ARTICLE YEAR:** 2008  
**COMPANY:** Lafarge Aggregates  
**COMPANY LOCATION:** Stansted Airport  
**COMPANY TEL:** 07803 953640

## TITLE

Bitumen delivery point improvement

## ARTICLE

Concerns were raised by employees after an incident involving a flange coupling failure at another site, which caused hot bitumen to spill during the filling operation.

A device was designed to overcome this that channeled the ,blow-out™ of bitumen safely downwards.

## ARTICLE IMAGES