

BEST PRACTICE

| | | | |
|--------------------------|-------------------|--------------------------|-----------------------|
| LOCATION: | Quarry | ARTICLE YEAR: | 2003 |
| ACTIVITY: | Working at Height | COMPANY: | Tarmac Southern |
| SUB ACTIVITY: | N/A | COMPANY LOCATION: | Hothfield Works, Kent |
| BEST PRACTICE No: | BP62 | COMPANY TEL: | 01233 611611 |

TITLE

Stairway improvement

ARTICLE

A steep staircase with a narrow tread and short risers led to several incidents of stumbling at Hothfield Works in Ashford. At first, a handrail along the length of the internal side of the stairway was fabricated CE but this alone did not solve the problem. After consultation with the companyTM's SHE department, alternating offset fall restriction barriers were extended into the stairway to reduce the risk involved.

ARTICLE IMAGES