

INCIDENT ALERT

LOCATION: ASPHALT/COATING PLANT
ACTIVITY: PRODUCTION AND PROCESSING
SUB ACTIVITY: ASPHALT & COATED STONE

ALERT STATUS: Normal
DATE ISSUED: 27/03/2007
INCIDENT No: 00125

TITLE

Bitumen Spill

COUNTRY OF ORIGIN

United Kingdom

ACCIDENT / INCIDENT DETAILS

The delivery tanker driver only tightened one of the 'bolts' on the flange that attaches to the rear of the tanker. When he commenced pumping the binder sprayed out from the 'lose' flange resulting in Contamination of bitumen tank, control panel, warning lights and system. It was extremely fortunate that no serious injury resulted from this incident.

ACCIDENT / INCIDENT IMAGES

Click image to enlarge



After the event

LEARNING POINTS / ACTIONS TAKEN

LEARNING POINTS / ACTIONS IMAGES