

**An unattended landrover rolled approximately 10 metres away striking a conveyor steel support beam.**

## **WHAT HAPPENED**

## **LEARNING POINTS / ACTIONS TAKEN**

---

<b>LOCATION:</b>	<b>QUARRY</b>	<b>ALERT STATUS:</b>	<b>Normal</b>
<b>ACTIVITY:</b>	<b>TRANSPORT &amp; LOGISTICS / DELIVERY</b>	<b>DATE ISSUED:</b>	<b>11/09/2024 18:28:28</b>
<b>SUB ACTIVITY:</b>	<b>DRIVING</b>	<b>INCIDENT No:</b>	<b>03763</b>