

Fatal 6 - TRANSPORT - Collision with parked vehicle

WHAT HAPPENED

Whilst travelling down a dual carriageway, service fitter van impacted broken-down refrigeration truck at 49 mph. Service fitter van was in the inside lane and misjudged gap between parked vehicle and traffic in outside lane (to be confirmed by CCTV).

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	ON-HIGHWAY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	30/05/2025 14:25:02
SUB ACTIVITY:	DRIVER AWARENESS	INCIDENT No:	04873