

Fatal 2 - TRANSPORT - FEL involved in collision

WHAT HAPPENED

FEL was operating in the stock pile area when they proceeded to drive with the bucket in the elevated position obscuring their vision. A tipper was incorrectly parked and the FEL operator was unaware of them, resulting in a collision between the FEL and tipper.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	STOCKPILING AND STACKING	DATE ISSUED:	05/06/2025 11:51:54
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04890