

Small landslip occurred whilst drilling

WHAT HAPPENED

Contractor carrying out drilling operations. As the first row of holes were drilled a small landslip occurred. After investigation it was found the area being drilled was unstable

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	05/06/2025 12:05:37
SUB ACTIVITY:	FACE ACTIVITY	INCIDENT No:	04893