

TRANSPORT - Telehandler runaway.

WHAT HAPPENED

Telehandler parked up in the workshop forecourt by the operator. After exiting the vehicle, approx 3 minutes later, the telehandler rolled away down the forecourt ramp where it came to a halt due to the forks digging into the ground. Estimated travel was 15m. Hand brake had not been applied.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	06/06/2025 12:13:20
SUB ACTIVITY:	BRAKES AND RUNAWAYS	INCIDENT No:	04896