

TRANSPORT - Dump truck runaway following hand brake failure

WHAT HAPPENED

Unladen Terex ADT rolled backwards 30m and impacted bund following suspected park brake failure. Operator had switched off the vehicle, and applied the park brake, whilst waiting on the haul road to be loaded

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY	DATE ISSUED:	06/06/2025 12:51:12
SUB ACTIVITY:	BRAKES AND RUNAWAYS	INCIDENT No:	04902