

Bitumen spillage during delivery

WHAT HAPPENED

Exposed to substance - Bitumen delivery, Tank1 100/150 overflowed during the last part of the delivery.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	ASPHALT/COATING PLANT
ACTIVITY:	TRANSPORT & LOGISTICS / DELIVERY
SUB ACTIVITY:	DELIVERING BITUMEN

ALERT STATUS:	Normal
DATE ISSUED:	10/06/2025 11:20:44
INCIDENT No:	04915