

BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2006
ACTIVITY:	Access & Egress & Working at Height	COMPANY:	Aggregate Industries
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Bardon Aggregates, Lancashire
BEST PRACTICE No:	BP365	COMPANY TEL:	07802 276 158
COUNTRY OF ORIGIN:	United Kingdom		

TITLE

CCTV cameras reduce tipper overturns

ARTICLE

One of the difficulties associated with the transportation and tipping of heavy loads is the overturning of articulated tippers. In an attempt to prevent overturns, Bardon Aggregates installed CCTV cameras in the front-inside of the vehicle body. The image is then relayed to a monitor in the cab. The driver can now observe, visually, the loading and discharging operations from the safety of the vehicle cab, assessing if there is likely to be any danger of the lorry tipping.

ARTICLE IMAGES

Click image to enlarge



vehicle tipping

Click image to enlarge



cctv image