

## BEST PRACTICE

LOCATION: Quarry  
ACTIVITY: Worker Involvement  
SUB ACTIVITY: N/A  
BEST PRACTICE No: BP387  
COUNTRY OF ORIGIN: United Kingdom

ARTICLE YEAR: 2006  
COMPANY: CEMEX  
COMPANY LOCATION: Hyndford Quarry, Lanarkshire  
COMPANY TEL: 01555 663597

### TITLE

**Welfare facilities**

### ARTICLE

Welfare facilities that had been present at this quarry since the 1960s had become progressively inadequate. With the strong involvement of the workforce, new facilities were developed, including:

- ? Canteen, first aid and training room
- ? Separate toilet and shower facilities for male and female employees
- ? On site water treatment
- ? Power and communication provision
- ? Car access, parking and pedestrian walkways ensuring segregation from large quarry vehicles.

The new buildings feature cavity block walls and tiled roofs with solar panels, which will give them a life-span beyond that of the quarry.

### ARTICLE IMAGES