

Working at height with no edge protection and inappropriate working platform

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: READYMIX OR MORTAR PLANT
ACTIVITY: ACCESS & EGRESS & WORKING AT HEIGHT
SUB ACTIVITY: N/A

ALERT STATUS: Normal
DATE ISSUED: 12/09/2024 13:00:42
INCIDENT No: 03780