

BEST PRACTICE

LOCATION:	Readymix or mortar plant	ARTICLE YEAR	2024
ACTIVITY:	Pedestrian and transport safety on-site	COMPANY:	Tarmac
SUB ACTIVITY:	No Sub Activity Available	COMPANY LOCATION:	Hopkins Bridgwater / Hopkins Wincanton
BEST PRACTICE No:	BP2248	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE

Out of hours cement deliveries - Topic 3 - Highly Commended

ARTICLE

TOPIC 3 - Highly Commended

Hopkins Bridgwater RMX is a busy concrete plant in the South West that supplies large volumes of concrete, bringing a large volume of vehicle movements in excess of 100 on busy days. This leads to congestion on site and challenges with VMPPM, along with having tanker drivers walking around their trucks in a busy yard.

Please see additional pdf for details of the design process

ARTICLE IMAGES