

BEST PRACTICE

LOCATION: Quarry
ACTIVITY: Production and Processing
SUB ACTIVITY: Aggregate processing
BEST PRACTICE No: BP146

ARTICLE YEAR: 2001
COMPANY: Aggregate Industries
COMPANY LOCATION: Buckton Vale Quarry, Cheshire
COMPANY TEL: 01457 835323

TITLE

Reduced glare for crusher operator

ARTICLE

At Aggregate Industries™ Buckton Vale Quarry, low sun angles significantly reduced the crusher operator™s view of the process. The remedy entailed the fabrication and fitting of fully adjustable external steel louvres. The gauge of the steel used was sufficient to withstand occasional flying rock fragments which, although the control cabin was fitted with toughened glass, had the potential to give the operator a shock.

ARTICLE IMAGES