

BEST PRACTICE

LOCATION: **ARTICLE YEAR:** 2008
ACTIVITY: Maintenance & Housekeeping **COMPANY:** Hanson
SUB ACTIVITY: N/A **COMPANY LOCATION:** Chipping Sodbury Quarry
BEST PRACTICE No: BP469 **COMPANY TEL:** n/a

TITLE

Aggregate Weigh Hopper Chains

ARTICLE

Further to the Near Miss Alert issued last month from Washington Premix, the following pictures highlight the protection systems necessary to prevent the sudden collapse of aggregate weigh hoppers.

ARTICLE IMAGES



are secured using a substantial bolt and safety pin design to prevent the weigh structure from falling, potentially onto a maintenance fitter or