

# BEST PRACTICE

**LOCATION:** **ARTICLE YEAR:** 2008  
**ACTIVITY:** Access & Egress & Working at Height **COMPANY:** Cemex North West  
**SUB ACTIVITY:** N/A **COMPANY LOCATION:** Gorton Manchester, Manchester  
**BEST PRACTICE No:** BP565 **COMPANY TEL:** 01928 752752

## TITLE

Pedestrian walkway

## ARTICLE

Gorton is a busy concrete batching plant in the Greater Manchester area, east of the city centre. Generally, the site provides large contracts within Manchester but a number of small trucks also visit the site on a daily basis.

The high level of traffic movement at the site was causing congestion, leading to a greater chance of injuries to pedestrians. The introduction of pedestrian walkways have provided safe areas in the plant.

## ARTICLE IMAGES

