

INCIDENT ALERT

LOCATION: Mobile Plant
ACTIVITY: Production and Processing
SUB ACTIVITY: Aggregate processing

ALERT STATUS: Normal
DATE ISSUED: 14/10/09
INCIDENT No: 00236

TITLE

Komatsu 350 & 400 ADT Failures

ACCIDENT / INCIDENT DETAILS

Left Komatsu 350 ADT failures / faults were identified in September 2008.

ACCIDENT / INCIDENT IMAGES



LEARNING POINTS / ACTIONS TAKEN

Always ensure your pre-start safety checks are completed thoroughly, pay close attention to load and stress points. Always ensure your mobile plant is inspected in accordance with the manufacturers recommendations.

The HM400 (above) was removed from service until the tail board could be removed safely.

Komatsu have been notified that a retro fit part fitted as a result of a previous alert has also failed. Komatsu are to investigate.

LEARNING POINTS / ACTIONS IMAGES