

Isolation Breach - Operative had followed LOTOTO and was cleaning in area 1. The operative was able to pass through from one lock-off zone to Area 2. When entering the new zone, the operative activated a sensor which started the plant (Precast)

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONCRETE PRODUCTS PLANT	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	03/09/2024 17:11:44
SUB ACTIVITY:	CONVEYORS	INCIDENT No:	03743