A concern was raised regarding the condition of a section of ducting (5t) which had been installed as part of the new bag filter project. Potential to fall.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: CEMENT PLANT ALERT STATUS: Normal

ACTIVITY: MAINTENANCE & HOUSEKEEPING DATE ISSUED: 12/09/2024 13:53:58

SUB ACTIVITY: CEMENT, LIME AND SLAG INCIDENT No: 03786