

Front End Loader (FEL) transporting product collided with a structural beam

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONCRETE PRODUCTS PLANT	ALERT STATUS:	Normal
ACTIVITY:	STOCKPILING AND STACKING	DATE ISSUED:	13/09/2024 11:53:42
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03796