

Guarding broke up under material spillage, this happened in an area above the stair case.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CEMENT PLANT	ALERT STATUS:	Normal
ACTIVITY:	PRODUCTION AND PROCESSING	DATE ISSUED:	13/09/2024 12:19:59
SUB ACTIVITY:	CEMENT PRODUCTION	INCIDENT No:	03801